HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NEB, 74-HUMB,

Reuel Nims Store Humboldt Richardson County Nebraska HABS No. NE-37

Documentation:

3 measured drawings (1980, including site plan)

8 exterior photos (1979)

5 interior photos (1979)

3 data pages (1986)

Don Standry, Photographer, August 1979

| NE-37-1 | GENERAL VIEW FROM SOUTHEAST, ACROSS POND |
|----------|--|
| NE-37-2 | GENERAL VIEW FROM SOUTHWEST, INCLUDING OUTBUILDING REMAINS |
| NE-37-3 | GENERAL VIEW FROM SOUTHEAST, INCLUDING RETAINING WALL |
| NE-37-4 | GENERAL VIEW FROM NORTHEAST |
| NE-37-5 | VIEW OF EAST SIDE |
| NE-37-6 | GENERAL VIEW FROM SOUTHEAST |
| NE-37-7 | VIEW FROM NORTHWEST, AFTER REMOVAL OF THE NORTHWEST ADDITION ONLY |
| NE-37-8 | WOODEN PORCH AT NORTH WALL |
| NE-37-9 | FLUE BREACHING FOR STOVE, EAST WALL OF ROOM 12 |
| NE-37-10 | ORIGINAL STAIR OPENING BETWEEN ROOMS 12 AND 23 FROM THE SECOND FLOOR |
| NE-37-11 | OLD SHELVES SUPPORTED BY TREE LIMBS, IN ROOM 02 |
| NE-37-12 | ORIGINAL STAIR OPENING BETWEEN ROOMS 12 AND 23 FROM THE FIRST FLOOR |
| NE-37-13 | DECORATED FLOORING AT NORTHEAST CORNER OF ROOM 21 |